

~~CONFIDENTIAL~~

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

REFERENCE: [REDACTED]

ATTACHMENT TO L-1543  
17 AUGUST 1966  
PAGE 1

LANDSLIDE AREA  
ROUTE 96, LAOS  
1535N 10655E

1. SIGNIFICANCE:

THIS BRIEFING BOARD DEPICTS A PORTION OF LAOS ROUTE 96 WHICH HAS BEEN MADE UNSERVICEABLE THROUGH INTERDICTIONS AND LANDSLIDES.

2. MISSION READOUT:

[REDACTED] REVEALS THAT ROUTE 96 IN THE AREA OF THE DAK E MEULE (RIVER) IS UNSERVICEABLE TO THROUGH VEHICULAR TRAFFIC DUE TO NUMEROUS INTERDICTIONS AND LANDSLIDES. PORTIONS OF THE ROAD ARE OVERGROWN. THIS UNSERVICEABLE PORTION OF THE ROAD EXTENDS FROM 1535N 10654E (UTM YC042240) TO 1534N 10656E (UTM YC074233). THE KAY BONG HIGHWAY FORD ON THE DAK E MEULE [REDACTED] IS UNSERVICEABLE.

[REDACTED]

ALL UTM COORDINATES ARE TAKEN FROM AMS SERIES L7012, SHEET 6357 I.

NGA review(s) completed.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

CONFIDENTIAL



NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER


LANDSLIDE AREA

Approved For Release 2006/02/27 : CIA-RDP79T0098A000100050001-5

15-35N 106-55E

25X1

25X1



25X1

25X1

REPRODUCTION OF THIS DOCUMENT IN  
WHOLE OR IN PART IS PROHIBITED  
EXCEPT WITH THE PERMISSION OF THE  
OFFICE OF ORIGIN.

C2-B-741